


***Missing "Kickout" or diverter flashings at roof-wall intersections are a common source of leaks behind stucco. The failure can be catastrophic.***



**Figure 4:** Diverter flashing at Roof / wall intersection

### **Diverter Flashing at Roof/Wall Intersection**

Where roofs and walls adjoin (figure 4) step flashing should be installed to keep water from entering the seam between them. Where the roofline terminates, the wall cladding immediately beneath it will suffer water intrusion unless an end piece of flashing with a bend in it is installed to divert water beyond the face of the cladding.